VILLAGE of WONEWOC

P.O. Box 37 · Wonewoc, WI 53968-0037 PH: (608) 464-3114 · FAX: (608) 464-7425

WISCONSIN PUBLIC SERVICE 2001 APR 27 A 9 40

RECEIVED

APR 2 7 760

Electric Division

April 26, 2001

Jim Loock, Chief Electric Engineer **Public Service Commission** 610 N. Whitney Way P.O. Box 7854 Madison, WI 53707-7854

RE:

In the Matter of Filing Plans for Appropriate Inspection and

Maintenance, PSC Rule 113.0607.

Dear Mr. Loock:

Enclosed for filing are 3 copies of Wonewoo Electric & Water Utility's Preventative Maintenance Plan detailing inspection maintenance schedules, condition rating criteria, corrective action schedules, record keeping procedures and report filing schedules as documented in this rule.

Very truly yours

Jeffrey J. Lankey, CMC

Village Administrator

Enclosures

WISCONSING THE TATIVE MAINTENANCE PLAN

2001 APR 27 A 9 40

RECEIVED

Wonewoc Electric & Water Utility

FILING DEADLINE FEBRUARY 1, 2001

April 26, 2001

RECEIVED

APR 2.7 2001

Electric Division

Don Hubele or Jeff Lankey 200 West Street Wonewoc, WI 53968 608/464-3114

wonewoc@mwt.net

This plan was prepared by the MEUW work group for PSC Rule 113.0607 for use by the 82 municipal electric utilities in Wisconsin and endorsed by PSC staff as meeting the requirements of Rule PSC 113.0607.

TABLE OF CONTENTS

		Page
I.	Preventative Maintenance Plan	2
II.	Inspection Schedule and Methods	2
III.	Condition Rating Criteria	3
IV.	Corrective Action Schedule	4
V.	Record Keeping	4
VI.	Reporting Requirements	4
VII.	Distribution – overhead inspection guide	5
VIII.	Distribution – underground inspection guide	8
	FORMS	
OVE	RHEAD DISTRIBUTION INSPECTION FORM	7
UND	ERGROUND DISTRIBUTION INSPECTION FORM	9

I. Preventative Maintenance Plan

The PSC 113.0607 rule reads;

Appropriate inspection and maintenance: system reliability.

- (1) PREVENTATIVE MAINTENANCE PLAN. Each utility or other person subject to this chapter, including persons who own electric generating facilities in this state who provide service to utilities with contracts of five years or more, shall develop and have in place its own preventative maintenance plan. This section is applicable to electric generating facilities as set forth at s. 194.491(5)(a)(1), Stats. Each plan shall include, among other things, appropriate inspection, maintenance and replacement cycles where applicable for overhead and underground distribution plant, transmission, generation¹, and substation facilities.
- (2) CONTENTS OF THE PLAN. (a) *Performance standard*. The Preventative Maintenance Plan shall be designed to ensure high quality, safe, and reliable service, considering: cost, geography, weather, applicable codes, national electric industry practices, sound engineering judgment and experience.
- 1 PSC staff interpretation is that generation applies to individual generators equal to or greater than 50 MW.

II. Inspection Schedule and Methods:

The purpose of this plan is to maintain or improve the electrical system reliability with the objective of increased municipal loyalty and satisfaction from our constituents. The goals are to meet and exceed the schedules established in this plan.

Exception reporting (inspected equipment not in good condition) will be the method of documentation on all inspection forms.

The scope of this plan is traditional and uses proven maintenance techniques. Unique operating and maintenance philosophies have not been considered. Also, manufacturer defects will be dealt with as they are communicated to this utility.

EVERY

SCHEDULE:	MONTHLY	ANNUAL	5 YEARS
Transmission (≥69Kv and above)			
Substations			
Distribution (OH & UG)			V
			Λ

The inspection of Distribution facilities will be by individual substation circuits on a 5-year cycle such that the entire system will be inspected every 5 years. Inspector instructions for inspecting all facilities and forms are included with the plan.

METHODS: Five criteria groups will be used to complete the inspection of all facilities.

- 1. <u>IR</u> infrared thermography used to find poor electrical connections and/or oil flow problems in equipment.
- 2. <u>RFI</u> Radio Frequency Interference, a byproduct of loose hardware and connections, is checked using an AM radio receiver.
- 3. <u>SI</u> structural integrity of all supporting hardware including poles, crossarms, insulators, structures, bases, foundations, buildings, etc.
- 4. <u>Clearance</u> refers to proper spacing of conductors from objects, trees and other utility cables.
- 5. <u>EC</u> equipment condition on non-structural components such as circuit breakers, transformers, regulators, reclosers, relays, batteries, capacitors, etc.

III. Condition Rating Criteria:

This criterion, as listed below, establishes the condition of a facility and also determines the repair schedule to correct deficiencies.

- 0) Good condition
- 1) Good condition but aging
- 2) Non-critical maintenance required normally repair within 12 months
- 3) Priority maintenance required normally repair within 90 days
- 4) Urgent maintenance required report immediately to the utility and repair normally within 1 week

IV. Corrective Action Schedule

The rating criteria as listed above determine the corrective action schedule.

V. Record Keeping

All inspection forms and records will be retained for a minimum of 10 years. The inspection form contains all of the required critical information i.e. inspection dates, condition rating, schedule for repair and date of repair completion.

VI. Reporting Requirements

A report and summary of this plan's progress will be submitted every two years with the first report due to the Commission by February 1, 2003. The report will consist of a letter documenting the percent of inspections achieved compared to the schedule and a description of maintenance achieved within the scheduled time allowance.

VII DISTRIBUTION - OVERHEAD INSPECTION GUIDE

STRUCTURE

- Pole Condition
- Pole Leaning
- Crossarm Condition
- Insulators, Deadend, Pin
- Excess Fill or Soil Removal
- Pole Steps
- Grounds Intact
- Ground Molding
- Down Guys
- Guy Markers
- Guy Bonding/Insulator
- Signage Location Number, Warning Sign
- Customer Equipment
- Conductor
- Tie Wires
- U Guard/Conduit Condition

EQUIPMENT

- Transformers
 - ✓ Oil Leaks
 - ✓ Bushing Condition
 - ✓ Grounding/Bonding
- Capacitors
 - ✓ Fuses Blown
 - ✓ Bushing Condition
 - ✓ Oil Leaks
 - ✓ Tank Bulged
 - ✓ Switches, Oil, Vacuum
 - ✓ Control Conduit/Wiring
 - ✓ Grounding/Bonding
- Switches GOAB, Inline, Disconnect
 - ✓ Insulator Condition
 - ✓ Operating Handle/Locks
 - ✓ Linkage
 - ✓ Grounding/Bonding
 - ✓ Switch Number
- Cutouts
 - ✓ Insulator Condition
 - ✓ Fuse Size Tag

VII DISTRIBUTION - OVERHEAD INSPECTION GUIDE (con't)

EQUIPMENT (CON'T)

- Arrestor
 - ✓ Insulator Condition
 - ✓ Connections
 - ✓ Ground Lead Disconnection
- Cable Terminators
 - ✓ Insulator Condition
 - ✓ Grounding/Bonding

CLEARANCES

- Ground Line
- Buildings, Bridges, Swimming Pool, Etc.
- Communications Facilities
- Fuel Tanks
- Other Electric Utilities
- Transmission Lines
- Over Streets, Roads, Alleys, Highways
- Tree Trimming
 - ✓ Clearance From Line
 - ✓ Vines on Poles
 - ✓ Danger Trees

INFRARED SCAN

- Main Three-Phase Feeders
- Priority Overhead Transformer Banks
 - ✓ Bushing Connectors Primary
 - ✓ Bushing Connectors Secondary
 - ✓ General Tank Heating
- Current & Voltage Transformers if Applicable

RFI CHECK

OH system with AM radio as each circuit is inspected

OVERHEAD DISTRIBUTION INSPECTION FORM

충

Sub

Inspected by_

Date

			 							—т						
	Corrected By															
	Date Item Corrected															
COMMENTS	Rating Criteria Color Condition 1) Good Condition but aging 2) Non-critical Maintenance Required 3) Priority Maintenance Required 4) Urgent Maintenance Required															
111	Communication Clearance															
	Streets, Roads, Alleys															
₹	Building Clearances															
CLEARANCE	Ground Line Clearances															
0	Tree Trimming															
	Street Light	·			_											
	Terminators							ļ								
EQUIPMENT	Arresters						L									
	Cutouts															
E	Switches															
	Transformer								<u> </u>					-		
	RFI Check		 ,			<u> </u>		<u> </u>				ļ				
	U'Guard/Conduit Cond		 					<u> </u>								
	Conductor and Ties					_	_		-							
	Customer Equipment			<u> </u>	 	-	-	 					 	 		
A H	Signs, Loc#, Warning		 		<u> </u>				-			-	-			
STRUCTURE	Guy Bond, Insulator	-	 			-	<u> </u>	<u> </u>							-	
S	Down Guys and Markers					-	-	\vdash	<u> </u>	<u> </u>		-	-	 		_
	Grounds Intact, Molding		 			\vdash	┼─	\vdash	-			 	 	\vdash		
"	Soil Conditions Pole Steps	-	 		-	\vdash	\vdash	\vdash	-				\vdash			
	Insulators, DE, Pin			-	-	-	-	-	 -	 		 		 	 	
	Crossam Condition		<u> </u>	 	_	\vdash	-	+-	\vdash		\vdash			\vdash	<u> </u>	
	Pole Condition/Leaning		 <u> </u>	-	T	\dagger			<u> </u>	 						
MAP AREA	LOCATION															

VIII DISTRIBUTION - UNDERGROUND INSPECTION GUIDE

STRUCTURAL (Exterior & Interior) Transformer, Primary Pedestal, Secondary Pedestal, Switchgear.

- Enclosure Condition
- Level/Leaning
- Security
- Grade/Accessibility (Shrubs, Customer Facilities, Fill/Excavation)
- Numbering
- Voids/Gaps
- Signage Location Number, Warning Sign
- Pad/Vault Condition

EOUIPMENT

- Transformers
 - ✓ Oil Leaks
 - ✓ Bushing Condition
 - ✓ Grounding/Bonding
 - ✓ Elbows
 - ✓ Arrestors
 - ✓ Feed-Through
 - ✓ Cable Condition
 - ✓ Secondary Connections
- Primary Pedestals
 - ✓ Elbows
 - ✓ Junction Condition
 - ✓ Grounding/Bonding
- Secondary Pedestals
 - ✓ Secondary Connections
- Switches URD Switchgear
 - ✓ Insulator Condition
 - ✓ Operating Handle Security
 - ✓ Linkage
 - ✓ Grounding/Bonding
 - ✓ Switch Number/Fuse Size & Number

INFRARED SCAN and RFI CHECK

- Main Three-Phase Feeders (Risers & Switchgear)
- Priority URD Transformer Banks
 - ✓ Bushing Connectors Primary
 - ✓ Bushing Connectors Secondary
 - ✓ General Tank Heating

		Сопесted By																
		Date Item Corrected																
Sub	COMMENTS	Rating Criteria 0) Good Condition 1) Good Condition but aging 2) Non-critical Maintenance Required 3) Priority Maintenance Required 4) Urgent Maintenace Required																
<u></u>	IR / RFI Scan	Priority URD Transformers, Bushings and Tank heating				ļ 		ļ		 								
Inspected by	IR/R	Main Three Phase Feeders, Risers & Switchgear						<u> </u>										
-Inspe		Switches, Signage, Insulators, Security, Linkage, Ground, Bonds																
	LNI	Secondary Pedestals, Connections												_				
Ф	EQUIPMENT	Primary Pedestals, Elbows, Grounding, Bonds, Junction cond.													<u> </u>			
RM Date	Ü	Transformers, Leaks, Bushings, Gond, Connections																
V FO		Rad / Vault Condition				<u> </u>	_		_	_		-	-	_	-	_		
TIO		əgsngi2			_		_		_	-	_	ļ	-	-	-	<u> </u>	ļ	$\frac{1}{2}$
UNDERGROUND DISTRIBUTION INSPECTION FOR	Ш	Voids / Gaps			_	_		-	_	-	1	╁	-	-	-	-	_	-
	CTUR	Mumbering			-	-	_	_	-	-	-	-	-	igdash	\perp	+	-	$\frac{1}{2}$
	STRUCTURE	Grade / Accessibility		<u> </u>	-	_	\perp	_	-	-	-	_	<u> </u>	-	-	+		$\frac{1}{2}$
		Security		$oldsymbol{\perp}$	-	-	_	_	_	\downarrow	-	+	+	-	_	-	 	$\frac{1}{1}$
ISTE		Level / Leaning		-	-	_	_	\perp	-	-	+	\perp	+	-	-	+-	-	$\frac{1}{2}$
		Enclosure Condition	 _	-	-	-	\downarrow	\perp	ig	-	\bot	+-	+-	\perp	+	-	-	$\frac{1}{1}$
UNDERGROUP	MAP ARFA	EQUIPMENT LOCATION																